SCANTRON®

OpScan® 4 ES and *i*NSIGHT™ 4 ES Updating Firmware

Important: You must install the driver software before updating the firmware.

Updating the Driver

1. Insert the **OpScan 4ES and *i*NSIGHT 4ES Utilities CD-ROM** into the CD-ROM drive of the computer.
2. **Browse** to your CD-ROM drive.
3. Double-click **setup.exe**.
4. Follow the on-screen instructions.
5. Click **Finish**.

Updating the Firmware

1. Insert the **OpScan 4ES and *i*NSIGHT 4ES Firmware Update CD-ROM** into the CD-ROM drive of the computer.
2. **Browse** to your CD-ROM drive.
3. Double-click **setup.exe**.
4. Follow the on-screen instructions.
5. Click **Finish**.

NOTES:

- Firmware version 4.7 or later requires the use of utilities version 1.5 or later.
- When updating SelfScore scanners from firmware version 4.6 or earlier, printer offset may need to be adjusted from "-5" to "0" if printing is too high.